H (High Quality) - Desirable urban tree species with vigorous growth and no apparent symptoms of disease or pests. MH (Medium-High Quality) - Desirable urban tree species with moderate

growth or minor symptoms of disease the are aesthetic only and less than 5% M (Medium Quality) - Any species with moderate growth and minor dieback of less than 20% of canopy and/or minor symptoms of disease or pests. ML (Medium-Low Quality) - Low vigour, with dieback of 15%-50% of canopy and/or major symptoms of disease or pests. L (Low Quality) - More than 50% of the canopy is dead.

Structural Condition H (High Quality) - No apparent defects to root crown, trunk, leader, or

major limbs. MH (Medium-High Quality) - Only insignificant defects to root crown or trunk and minor defects to canopy including limbs. M (Medium Quality) - Minor defects to root crown, trunk and major

ML (Medium-Low Quality) Major defects to long-term structure particularly at root crown, trunk and major limbs. L (Low Quality) - Major defects that have an immediate risk of failure.

R - Remove for poor condition RC - Remove for Construction R* - Remove with Neighbour's Approval

Location Designation S - Subject site P - City-owned Park C - City-owned Boulevard B - Boundary tree

TREE PROTECTION RECOMMENDATIONS:

- Install hoarding for subsequent municipal
- Hoarding may be moved temporarily to provide and breaking of roots of trees to remain.
- Pruning, if required, should be done prior to construction and in accordance with current arboricultural practices.
- and disposal of liquids is not permitted within 1m of protected areas.
- Excavation in close proximity to protected areas are
- Roots encountered due to excavation are to be cut with a clean sharp blade. Tearing and ripping of roots is not permitted.
- Exposed roots are to be covered immediately with
- Deep root fertilize (3:1:1) following backfilling. Trees should be re-assessed periodically in order to

BF Backfilled

- CS Compacted soil DB Dead branches G Girdling HA Hazard
- IB Included bark _° LS Lean showing direction (i.e. LS=lean south) 2L 2 leaders or codominant stems MB Multibranched node MS/ML Multistem
- PL Pruned limbs SU Supressed crown Torn/broken branch TD Trunk damage (percent of
- trunk circumference) TH Top heavy UB Unbalanced crown (N,S,E,W indicates weighted side of
- V Vine growing in tree WB Witches broom growth WP Woodpecker damage
- WS Watersprouts ZZ Zigzag trunk %D X% crown is dead

- review/approval. access for tree removal only. These trees should be felled away from protected areas to avoid pulling
- Storage of any materials, fill, vehicles/equipment,
- to be undertaken with a certified arborist present.
- Hydrovacing is recommended as the preferred method for excavation. within 1m of protected
- maintain an up to date understanding of health and structure.


mulch or topsoil and watered thoroughly. A light

coloured tarpaulin may also be used to prevent root

ROOT SENSITIVE EXCAVATION -----Trench to be dug at the limit of excavation. 20cm wide and 1m deep or to the depth of excavation

- (whichever is less), dug by hand or with a hydrovac prior to excavation to
- establish the boundary of future excavation. While digging this trench roots that are encountered that extend into the area to be excavated may be cut with a sharp cutting tool. There shall be no use of blunt tools or construction
- Once dug, the side of the excavated trench closest to trees being protected must be covered following one of two approaches. Option 1: re-fill with native soil, backfilled using lifts of 15 cm, tamped by hand, and soaked. Option 2: Sprayed with a light mist to add moisture without causing erosion and covered with a light-coloured tarpaulin to preserve moisture in the soil.

equipment to cut the roots. There shall be no pulling or ripping



NOTES: 1. Hoarding details to be determined following initial site inspection.

- 2. Private tree hoarding to be approved by Development & Design; City tree hoarding to be approved by Community Services Dept.
- 3. Hoarding must be supplied, installed and maintained by the applicant throughout all phases of construction. Inspection must be conducted by the Development and Design Division prior to removing any/all private hoarding.
- 4. Do not allow water to collect and pond behind or within hoarding. 5. T-bar supports are acceptable alternative to 4x4 posts. U-shaped metal supports will not be accepted.
- 6. Plywood must be utilized for 'solid' hoarding. OSB/Chipboard will not be accepted for solid hoarding. Plywood sheets
- must be installed on "construction" side of frame. 7. Applicant is responsible to ensure utility locates are completed within city boulevard prior to installing framed hoarding.

TREE PRESERVATION HOARDING

SCALE : N.T.S DATE : June 2017

Mississauga


		(E	Canopy diameter (m)	Bioglogical Health	Structural Condition	Recommended Action	ents	Existing Location Designation	Future Location Designation
Tree No.	Species	ОВН (сm)	(doue	oolbo	ructu	comi	Comments	isting	ıture
<u> </u>	gs	DIG	Ü	Bi	St	Re	Large wound at base, 15% dia trunk	<u> </u>	-3
1	Acer platanoides	26	6	M	M	Р	damage, Backfilled, and one medium- sized dead branch.	C	C
2	Juglans nigra	102	15	МН	МН	Р	Grown over former fence still embedded in trunk, large hole/wound at 1 m (15cm dia), some broken branches in interior of canopy but vigorous growth for size. Oe large crack and injury in upper canopy on	С	C
3	central leader. Wounds from fence. Main union is in poor condition with 2 long healed cracks branches and one large broken branch.		С	С					
1	Morus alba	15 15 5	7	NALL.	ML	RC	10% of canopy covered in vine. Multistem tree with included bark at unions. Leans towards park site. Some	С	C
4	INIOI US AIDA	15, 15.5		MH	IVIL	NC .	crossing branches.		
5	Aesculus hippocastanum	35	5	ML	ML	RC	Growing through fence and vine covers 70% of canopy.	Р	Р
6	Acer platanoides	22, 11	6	ML	ML	RC	Vine covers 70% of canopy and one medsized dead branch.	Р	Р
7	Acer platanoides	31	6	М	М	RC	Growing through fence mesh and has thicket creeper in canopy.	Р	S
8	Acer saccharinum	32, 44.5	10	МН	М	RC	Co-dominant leaders, two large dead branches, growing through fence mesh.	Р	S
9	Acer platanoides	~32	10	М	М	RC	Growing through fence mesh, leans 10° to north east.	Р	S
1.0	A1	24 4==	~			D	Co-dominant leaders with included bark	-	
10	Acer platanoides	31, 46.5	9	М	М	RC	at base to 30cm ht. Leans 10° to north west. Has girdling root at base.	Р	S
11	Acer platanoides	22	6	М	ML	RC	Grows through fence mesh, suppressed, and leans 10° to north west.	Р	S
		14, 15x2,					Multistem tree with included bark between all trunks. Girdling roots across		
12	Acer platanoides	18x2, 19x2, 15, 26.5	10	М	ML	RC	the base. Three large injuries from fuse branches.	Р	S
13	Acer platanoides	25, 33	8	М	М	RC	Included bark at base, leans 10° to east and a girdling root.	Р	S
14	Acer platanoides	16	4	М	М	RC	Girdling root with tree #13 and has a small canopy.	Р	S
15	Acer platanoides	91.5	15	М	ML	RC	Girdling root across 50% of base and over 15 medium-sized dead branches.	Р	S
16	Acer platanoides	15.5	6	М	М	RC	45°L to east, slight canopy with 50% of	Р	S
17	Acer negundo	19.5	5	ML	ML	RC	branches with tip dieback.	Р	S
18	Acer negundo	22.5	7	М	М	RC	Fused with another small tree at base to 1m ht.	Р	S
19	Acer negundo	35.5, 40	9	М	М	RC	Co-dominant leader with one leader leaning 45° to north east. Some grape vine covers 5% of canopy.		S
20	Fraxinus pennsylvanicus	14	5	MH	М	RC	Grape covers the lower 25% of canopy, but no EAB obvious yet.	Р	S
21	Acer platanoides	17	5	М	ML	RC	Supporting tree #22 and grows through a fence mesh.	Р	S
22	Acer negundo Acer platanoides	27.5	8	M	ML ML	RC RC	45°L to south on tree #21. Large central leader cut at 1.7m ht. an and wound from cut on remaining leader. Has included bark from 0.5 to 1.7m ht. One leader leans 30° to south. Has several small dead branches.		S
24	Acer platanoides	35, 41	12	М	М	RC	Included bark from 1m to 1.7m, tight branching causing injury from fusing trunk.	Р	S
25	Acer negundo	23	6	M	ML	RC	Leans 45° to north east and has a sparse	Р	S
26	Gleditsia tricanthos var.	62	16	Ĥ	Н	RC	canopy.	5	5
	inermis Acer negundo	35	7	M	M	RC	Many 10 small dead branches. Large pruned limb at 4m, medium-sized	S	S
	Acer negundo	32	7	M	M	RC	wound at base of 3% trunk damage. Medium-size wound from cut co- dominant leader covering 15% trunk		5
20	TI :	25x 2,	5			D.C.	damage. Girdling root also present.	-	
29 30	Thuja occidentalis (Hedge) Acer negundo	30x5, 15x2	4	MH	M H	RC RC	All multi-stem from 0.5m height. Leans 15° to west.	S	В
31	Thuja occidentalis	20.5	5	M	M	RC	45oL to south west and 20% trunk wounded.	С	С
32	Thuja occidentalis	16	3	ML	M	RC	Suppressed.	C	В
33	Acer negundo	78	17	М	ML	RC	45oL, with more than 6 large branches cut of over 15cm dia. Also 2 large cuts of	S	S
34	Fraxinus pennsylvanicus	25, 25				R	30cm dia. DEAD	S	S
	Acer negundo	44	9	М	М	RC	Tip dieback of 10% and 2 large dead branches.	S	S
	Fraxinus pennsylvanicus	14	-			R	DEAD tip dieback of 10% and 2 large dead	S	5
37 38	Acer platanoides Acer platanoides	28, 38	9	MH	M	RC RC	branches. Large prune cut of 15cm at 2m	S	S
	Acer platanoides	22	6	МН	M	RC	Large wound at 30% trunk damage at root crown.	S	S
40	Acer platanoides	32	9	MH	М	RC		S	S
	Acer platanoides Fraxinus pennsylvanicus	23 ~30	6	MH	MH	RC R	Small dead branches and small cuts at base. DEAD	S S	S S
13A	Acer platanoides	~15	6	MH	MH	RC	45° lean to south, branch fused creating wound at 43A.	S	S
	Acer platanoides Fraxinus pennsylvanicus	~25 ~30	6	MH	MH	RC R	10°L to west.	S	S
45	Acer platanoides	20	7	MH	MH	RC	Hanging branch in canopy.	S	S
	Fraxinus pennsylvanicus Fraxinus pennsylvanicus	~30 ~35				R R	DEAD DEAD	S S	S
	Acer platanoides	29	9	MH	MH	RC	Backfilled and unbalanced canopy to east.	S	S
	Acer platanoides Acer platanoides	17 31	5 7	H MH	MH M	RC RC	Crack from 0.5m to 2m, unbalanced canopy to west and second crack from	S	S
	Picea pungens	39	4	М	М	RC	2m to 4m ht. Backfilled.	S	S
	Picea pungens	46	4	М	ML	RC	Large wound of 15% of trunk diameter at base with sawdust and backfill over base.	S	Р
53A	Morus alba	18	5	М	М	RC	slight canopy and unbalanced crown to	S	Р
	Fraxinus pennsylvanicus	14	100.0			R	south. DEAD crack from 1m to 1.5m ht.	S	В
	Acer platanoides	21	6	MH	MH	Р	4 5 1	S	P

1:200

Tree No.	Species	DBH (cm)	Canopy diameter (m)	Bioglogical Health	Structural Condition	Recommended Action	Comments	Existing Location Designation	Future Location Designation	Tree No.		
57	Ailanthus altissima	51	8	Н	МН	Р	large pruned limb with ripping wound and two other medium-sized broken branch wounds.	S	Р	70		
58	Morus alba	35	8	M	M	Р	leans 30° to south.	S	Р		70	
59	Ailanthus altissima	17	4	H	Н	RC	unbalanced canopy to south.	S	Р	71	71	
60	Acer platanoides	16	4	М	M	RC	backfilled, has 5 small prune cuts and a thin wound from 30cm to 1m ht.	S	Р	7.1	71	
61	Acer platanoides	20.5	4	MH	MH	RC		S	S	72	72	
62	Acer negundo	19.5	5	M	M	RC	30° lean to south, one dead trunk fallen.	S	S			
63	Acer platanoides	35	6	MH	MH	RC		S	S	73	\rightarrow	
64	Salix alba 'Tristis'	19	4	М	ML	RC	multibranch node.	S	S	74	\rightarrow	
65	Salix alba 'Tristis'	25	6	MH	M	RC	10°L to north east.	S	S	75		
66	Ulmus americana	44.5	8	L	L	R	50% of canopy is dead. Vine is covering 50% of remaining canopy.		Р	76		
67	Gingko biloba	131.5	18	L	L	R	80% of canopy dead. Three leaders and included bark from base to 2m height also at 4 to 8m ht. Large cut at 1m height.	S	Р	77 78 79 80		
68	Malus sp.	29, 17	7	МН	МН	Р	10% trunk damaged at 30cm ht. and greater than 2 medium-sized dead branches.	S	S	81		
69	Malus sp.	10, 10	6	М	ML	Р	Leans 45° to east.	C	C		Tr	

	Existing Location Designation	Future Location Designation	Tree No.	Species	DВН (ст)	Canopy diameter (m)	Bioglogical Health	Structural Condition	Recommended Action	Comments	Existing Location Designation	Future Location Designation
wound oken	S	P P	70	Acer saccharinum	126.5	18	ML	М	Р	Three of eight leaders showing dieback, central trunk largely dead with tight branches at multibranch nodes, but no included bark	С	С
ts and a	S	Р	71	Prunus avium	29.5	7	M	ML	Р	large prune cut at 1.5m height and 15° lean to south.	С	C
nt. nk fallen.	S S	P S S	72	Prunus avium	22, 23.5, 25, 31	9	МН	ML	Р	Multi-leader with included bark at base of trunk with 2 of 4 limbs leaning 45° to south east and south west.	S	Р
	S	S	73	Picea pungens	24.5	4	Н	Н	Р		S	Р
	S	S	74	Picea pungens	25	4	Н	Н	Р		S	S
	S	S	75	Picea pungens	32	5	Н	Н	Р		S	S
covering	S	Р	76	Acer platanoides	14.5	4	МН	МН	RC	Medium dead branches and small injuries at 6m height.	S	C
ders and			77	Thuja occidentalis	20, 15x3	3	М	МН	Р	tight unions	C	C
height			78	Thuja occidentalis	22	3	M	MH	Р		C	C
1m	S	P	79	Thuja occidentalis	15.5	2	М	МН	Р		C	C
			80	Thuja occidentalis	16,16, 19	3	М	MH	P	tight unions with included bark	C	C
t. and			81	Thuja occidentalis	15, 18	3	М	МН	Р	tight unions with included bark	C	C

Trees less than 15cmØ caliper, and large shrubs may exist on the site. It is the contractors responsibility to determine the extent of possible removals by field review prior to submission of quotations for removals work.



LEGEND --- Property Line Proposed Extent of Underground Parking Slab Tree protection -solid hoarding Tree protection -framed hoarding Root Sensitive Excavation Trench Existing tree to be removed

LIMITING CONDITIONS:

This tree inventory was derived from data gathered on the site using accepted arboricultural practices. This includes a visual examination of all above ground parts of the tree for structural defects and signs of health and vigour. All examination took place from the ground plane and no trees were cored, probed or climbed. There was also no detailed inspection of the root crown where excavation would have been required.

This inventory describes the health, structural stability and identifies potential hazards of the trees to a reasonable extent. Where dead branches or other are identified in the notes it is the owners responsibility to take action. This inventory does not provide or imply a guarantee that these trees or branches will remain standing intact. The stability

Existing tree to be removed

Dead, girdled or dangerous.

Existing tree to be preserved

of any tree or branches of a tree cannot be predicted with absolute certainty under all There is, likewise, no guarantee of survival for those trees to be preserved during construction but which are subject to injury. Tree preservation guidelines that are provided in this report are generally suitable for the tree as determined by the visual assessment. However, there is no guarantee that these guidelines will be followed throughout construction unless an arborist is retained for complete supervision of the site at all times. Even with complete supervision, roots in an urban environment are

unpredictable. Guidelines, that suppose an even distribution of roots may not be

The assessment in this inventory is valid only at the time of inspection.

effective in cases where roots have clustered in small areas.



ISA Certified Arborist ON-1439A

REVISIONS


14 Jun 2024 Issued for Client Review

09 Dec 2021 Issued for OPA & Zoning Submission #1

18 Aug 2020 Issued for Client Review DATE DESCRIPTION

NOTE: Contractor is to check and verify all dimensions and conditions on the project, and is to immediately report any discrepancies to the landscape architect before proceeding with the work.





Tel: (905) 453-9398

Web: bakerturner.com

email: tba@bakerturner.com

Landscape Architecture | Site Design

Suite 234 2010 Winston Park Drive Oakville Ontario L6H 5R7

Project Title 10 WEST GO GP INC.

17 & 19 Ann St.; 84 & 90 High St. Mississauga, ON

TREE INVENTORY & PRESERVATION PLAN

Date August 2020	ssued
Job Number	Drawn By
BTI-1490	KC
Scale	Checked By
As Shown	JW/TT
Sheet Number TS.1	File Number

TREE PRESERVATION HOARDING