



Consulting Geotechnical & Environmental Engineering Construction Materials Inspection & Testing

June 19, 2023

File No. 1-19-0719-46.1 Brampton Office

Manager, Environmental Site Management & Compliance Environmental Services Transportation & Works Department City of Mississauga 201 City Centre Drive, 8th Floor Mississauga, Ontario L5B 2T4

RE: LETTER OF RELIANCE HYDROGEOLOGICAL ASSESSMENT 2570-2590 ARGYLE ROAD, MISSISSAUGA, ONTARIO L5B 1V2

To whom it may concern,

We are the authors of the report entitled,

HYDROGEOLOGICAL ASSESSMENT 2570-2590 ARGYLE ROAD MISSISSAUGA, ONTARIO L5B1V2 Dated: February 23, 2022, Our File No.: 1-19-0719-46.1

in reference to the above-noted property. Terraprobe Inc. (Terraprobe) prepared the referenced Report (the "Report"), for the sole use and benefit of *Ranee Management* (our client), for the referenced Project, subject to the general limitations noted in the report. At the request of our Client, in order to support and facilitate, the Project, and subject to the terms of this letter, Terraprobe hereby authorizes "*City of Mississauga*" to use and rely upon the Report to the same extent and in the same manner as if it had been addressed to the Relier at the time of its issuance.

The Report was prepared in accordance with applicable, customary and generally accepted professional and technical standards ordinarily exercised by other engineering professionals providing similar services under similar circumstances in the location and at the time the subject services were provided and the Report prepared. Terraprobe makes no representations or warranties regarding compliance with any other standard(s). *City of Mississauga's* reliance upon the Report is subject in all respects to this letter, the conditions and limitations set forth in the Report and Terraprobe's General Terms and Conditions applicable to the Report. The use of the Report constitutes acceptance of the foregoing.

| Terraprobe Inc. | | | |
|------------------------------|------------------------------|------------------------------|------------------------------|
| Greater Toronto | Hamilton – Niagara | Central Ontario | Northern Ontario |
| 11 Indell Lane | 903 Barton Street, Unit 22 | 220 Bayview Drive, Unit 25 | 1012 Kelly Lake Rd., Unit 1 |
| Brampton, Ontario L6T 3Y3 | Stoney Creek, Ontario L8E | Barrie, Ontario L4N 4Y8 | Sudbury, Ontario P3E 5P4 |
| (905) 796-2650 Fax: 796-2250 | (905) 643-7560 Fax: 643-7559 | (705) 739-8355 Fax: 739-8369 | (705) 670-0460 Fax: 670-0558 |
| www.terraprobe.ca | | | |

It should be noted that the Report is representative of the site conditions at the time of the field investigation (January 09, 2020). We cannot comment on any changes that may have occurred to the site subsequent to our site investigation and are not responsible for any implications thereof. Any use of the Report is subject to the general limitations noted in the Report. The Report may not be used for purposes other than those expressly stated in the Report.

Reliance on and/or use of the Report constitutes acceptance of the foregoing, and the terms and limitations noted in the subject Report.

Yours truly,

Terraprobe Inc.

R. Baker Wohayeb, M.A.Sc., P.Eng. QP_{RA} Principal

